

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- 1 Name of the Officer : RASHY .P.R
- 2 Name of the School : Norte Dame School, Vettikuzhy, Chaippinkuzhy
- 3 Location with name of Education District/
Sub. District : Thrissur/Chalaky
- 4 Classification of Building as specified in
column 4 of the application for fitness
certificate and size. : Permanent Multi-storied Building (GF+FF)
(New Block)
- GF = 8 Class rooms of 6.00x6.80m
1 Class Room of 12.00x6.80m
- FF= 4 Class rooms of 6.00x6.80m
1 Class Room of 12.00x6.80m
- 5 Period for which the certificate is issued : Upto 31-Mar-2022
- 6 Nature of defects , if any
- a) Foundation and basement : :
b) Superstructure : :
c) Doors and Windows : :
d) Wood work wrought and put up : :
e) Roof : :
f) Flooring : :
g) Miscellaneous (Cracks, etc.) : :
Nil
- 7 Any major defects noticed which will render
the building unsafe in any manner : Nil
- 8 Whether maintenance works have been done
properly : Yes
- 9 Whether the structure is sound or not for
conducting classes : Sound under normal weather conditions

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.


CERTIFICATE

Certified that the school building was inspected by me on 15-Jun-21 and found to be fit to conduct classes, for the period upto 31-Mar-2022 for the reasons stated above.

Vettilappara
15-Jun-21

Sr. Seemita

MANAGER
NOTRE DAME SCHOOL
VETTIKUZHY
CHAIPPANKUZHY (P.O), CHALAKUDY
THRISSUR (DT), KERALA - 680724



[Signature]
ASSISTANT ENGINEER
LSDO (EM) SECTION
ATHIRA PULLA
SR. RANJANA
PRINCIPAL
NOTRE DAME SCHOOL
VETTIKUZHY
CBSE Code No:- 930884
CHAIPPANKUZHY P.O., PIN-680724
THRISSUR, KERALA

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- 1 Name of the Officer : RASHY .P.R
2 Name of the School : Norte Dame School, Vettikuzhy, Chaippinkuzhy
3 Location with name of Education District/
Sub. District : Thrissur/Chalaky
4 Classification of Building as specified in
column 4 of the application for fitness
certificate and size. : Permanent Multi-storied Building (GF+FF+SF)
(Old Block)
GF = 895.86 m²
FF = 886.71 m²
SF = 825.12 m²

- 5 Period for which the certificate is issued : Upto 31-Mar-2022
6 Nature of defects , if any :
a) Foundation and basement :
b) Superstructure :
c) Doors and Windows :
d) Wood work wrought and put up :
e) Roof :
f) Flooring :
g) Miscellaneous (Cracks, etc.) :
7 Any major defects noticed which will render : Nil
the building unsafe in any manner
8 Whether maintenance works have been done : Yes
properly
9 Whether the structure is sound or not for : Sound under normal weather conditions
conducting classes

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 15-Jun-21 and found to be fit to conduct classes, for the period upto 31-Mar-2022 for the reasons stated above.

Vettilappara


15-Jun-21

Sr. Seemita

MANAGER

**NOTRE DAME SCHOOL
VETTIKUZHY**

**CHAIPPANKUZHY (P.O), CHALAKUDY,
THRISSUR (DT), KERALA - 680724**



S. K. S. S.
S. K. S. S.
**ASSISTANT SUPERINTENDENT
LOCAL (E) SUPERINTENDENT
NOTRE DAME SCHOOL
ATHIRAPATTI, VETTIKUZHY
CBSE Code No: 930884
CHAIPPANKUZHY P.O., PIN-680724
THRISSUR, KERALA**