FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer) (G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Name of the Officer

: RASHY .P.R

2 Name of the School : Norte Dame School, Vettikuzhy, Chaippinkuzhy

Location with name of Education District/ Sub. District

: Thrissur/Chalakudy

Classification of Building as specified in column 4 of the application for fitness

certificate and size.

: Permanent Multi-storied Building (GF+FF) (New Block)

GF =

8-Class rooms of 6.00x6.80x3.75m

1-Class Room of 12.00x6.80x3.75m

FF

4 Class rooms of 6.00x6.80x3.75m

1 Class Room of 12.00x6.80x3.75m

Period for which the certificate is issued

: Upto 31-Mar-2024

Nil

Nature of defects, if any

a) Foundation and basement

b) Superstructure

c) Doors and Windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks, etc.)

Any major defects noticed which will render

: Nil

the building unsafe in any manner

Whether maintenance works have been done

properly

: Yes

Whether the structure is sound or not for conducting classes

: Sound under normal weather conditions


Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 20-May-23 and found to be fit to cond classes, for the period upto 31-Mar-2024 for the reasons stated above.

Vettilappara 20-May-23

> NOTRE DAME SCHOOL VETTIKUZHY CHAIPPANKUZHY (P.O), CHALAKUDY THRISSUR (DT), KERALA - 680724



RE DAME SCHOOL (DT), KERALA - 680724 Email-notredamevettikuzhy@ymail.com BSISTANT ENGINEER LSGO (EW) SECTION ATHIRAPPILLY THRISRUR 680 120